

## Update RAP

Given provision for PPIO to update or correct the key parameters of the loco under 'corrections' main menu.

- Click on Update RAP under Correction Menu.
- Update RAP page displays

### Update RAP

**Type**                      **Status**                      **Section**                      **From**                      **To**

- Select Type, Status, section, from date and to date
- Click on go option.

S.No	Check No	Section	Subject	Action To Be Done	Remarks	Reference	Target Date	Total Done
1	RA/13/2017	E5	REPLACEMENT OF CGR CONTACT BOLT ONE CYCLE	ALL 5 CGR FRAME CONTACT BOLTS TO BE CHANGED WITH NEW ONE DURING OVERHAUL OF CGR FRAME		LOCAL RAP AFTER FAILURE OF CONTACT BOLT HEAD BROKEN	23/09/2018	0 61
2	RA/11/2017	RR1A	Provide Fireball in all P4 loco during major schedule	clamp to be fabricated base to be welded in loco near GR fireball to be fitted		ADEE instruction	23/09/2019	0 8
3	RA/17/2017	E6	Checking of Double connection at single terminal on Limit Switches	check for double connection at single terminal on limit switched of Loco. If found, the inform to E7 spl for making it single by laying wire from origin SB	only one connection to be allowed on limit switches	Sr Dee Instruction in meeting dated 10.11.2017	10/11/2019	0 0
4	RA/21/2017	E7RR	MAINTAIN GAP BETWEEN ALIX INTERLOCK AND LEVER OF LINE CONTACTOR(1.5 TO 2MM)	MAINTAIN GAP BETWEEN ALIX INTERLOCK AND LEVER OF LINE CONTACTOR(1.5 TO 2MM) TO STOP THE PROBLEM OF 'NOTCH COMING BY BPP AND EEC WHILE MP ON 0		LOCAL RAP	05/12/2019	0 13
5	RA/24/2018	E7SPL	Check for cable damage/cut near Arno base and other sharp edges.	Check for cable damage/cut near Arno base and other sharp edges. Sharp edges to be rounded by providing/welding small round edge cleat.		failure OPR dec17-jan18	04/01/2019	0 191
6	RA/16/2019	E2SPL	SIV of SIEMENS TCD to be replaced	SIV of SIEMENS TCD to be replaced	Loco number 27518	Local RAP	31/12/2019	0 0
7	RA/100/2019	MSR	BP additional angle cock maintenance	to ensure BP additional angle cock free movement, lubrication and its locking during maintenance	to prevent problems of BP addtl cock in case of CRO	14.05.2019 case of CRO of GZB loco 30040	30/09/2019	0 3
8	RA/11/2019	MSR	BP additional angle cock testing	to ensure no leakage form vent hole of BP additional angle cock in closed position and its sealing	to prevent BP addtl cock malfunction in case of CRO	14.05.19 CRO case of GZB loco 30040	30/09/2019	0 8
9	RA/37/2020	E5	RTV apply on roof on entry of cable of harmonic filter resistance	Apply rtv on the entry point of cable for harmonic filter cable on roof to prevent water ingress	To be done by e5 during inspection of three phase locos	Failure of loco 37100 on shed arrival on 17-01-20	30/05/2020	0 98

- Click on Check No link to update RAP details.

### Update RAP

Check For     Locos     Equipment    For section   

Loco Types        Schedules   

Select Locos   

Subject   

Attachments        No file chosen

Action to be Done   

Reference   

Remarks   

Date Start        Target Completion

- Enter all the details and click on save option.