

USER MANUAL FOR HQ TLC

CRIS

Contents

Table of Contents

1. Administration.....	3
1.1 Change Password	3
2. Loco Failures.....	4
2.1 Asset Failures (ICMS) ownership.....	4
2.2 Asset Failures (ICMS) Territorial	7
3. Locos.....	10
3.1 Find a Loco	10
3.2 Loco History.....	10

Go to this URL-slam.indianrail.gov.in/SLAM/Login.aspx
And login with your user id and password which you received.

1. Administration

1.1 Change Password

User can change the password by following the below mentioned steps –



Change Password Sections

1. Click on Administration side menu and select "Change Password" Sub menu.
2. "Change Password" screen is displayed.
3. Enter the Current Password, New Password and Confirm New Password.
4. Click on **Save** button to save the details, successful message is received.
5. The Password will be changed to current one.


Change Password	
Employee Name	TLC NDLS Admin
Login Name	tlcndlsfh
Current Password	<input type="password" value="....."/>
New Password	<input type="password" value="..."/>
Confirm New Password	<input type="password" value="..."/>
<input type="button" value="Save"/>	

Change Password

2. Loco Failures

2.1 Asset Failures (ICMS) ownership

Click on asset failures ICMS ownership under Loco failures



It shows the records of one particular division (Home shed) ICMS Failures which can be updated in that particular division.

View Asset Failure (ICMS) Ownership

Loco Loco Kind Loco Type ICMS Sub Group Status Zone(Territorial) Division(Territorial) Shed(Ownership) From To

 --All-- --Select-- --All-- --All-- --All-- --All-- --All-- 09/01/2023

Enter all the required details and click on go option.

View Asset Failure (ICMS) Ownership

Loco Loco Kind Loco Type ICMS Sub Group Status Zone(Territorial) Division(Territorial) Shed(Ownership) From To

 --All-- --Select-- --All-- --All-- --All-- --All-- --All-- 09/01/2023

Showing 20 Record(s) Out of 46

S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding	Classification of Case	Home Rly	Equipment
1	08/01/2023 04:00 AM	ONCR	23351/VAG5		DFCC/EDFC	SJTN-SJTN	SJTN-SJTN	KN-22/23351/3557 TRAIN IS CONTROLLED DUE TO SLOW RECEPTION BY IR SJT			Yet To Be Classified	WCR/JBP/NKJ(D)	Update
2	08/01/2023 03:15 AM	ELFG	23887/VAG5T		NR/DLI	JIND	JIND	MKS/FBD POWER NO-23887+23639 AFTER PASSING STR STOP THE LOAD AND LOCO TROUBLED REP 19803/ 12138 SUFFERD			Yet To Be Classified	WCR/JBP/NKJ(D)	Update
3	07/01/2023 06:15 PM	ECRW	27114/VAG7		NWR/BKN	KSI	KSI	TKD WITH DSL 27114 AT KSI, FOR CREW, FROM 18/15 TO 00/00 HRS.			Yet To Be Classified	WCR/JBP/NKJ	Update
4	07/01/2023 10:25 AM	ELTG	23786/VAG5		NER/BSB	GKC-CPR	CPR	DN AZA/23786+23668/NKJ/13/2 CPR arrived at 10.25 out at 13.10.detained due to power trouble U1, U2, A3 miter not working and VCD isolated fault in 2nd LOCO while DJ holding same attached by CLI.			Yet To Be Classified	WCR/JBP/NKJ(D)	Update

Click on [Loco number link](#) to update HQ TLC Remarks.

Click on [Rly\(Zone\)Action link](#) to update

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
31098	WAG9H	Select	AQE	IOH	04/10/2023	ELS / AQE	IC	02/06/2023	ELS / AQE	--	--Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification: Yet To Be Classified Railways (ZONE) Action Failure Responsible: --Select--

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

Save

To update Classification

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
31098	WAG9H	Select	AQE	IOH	04/10/2023	ELS / AQE	IC	02/06/2023	ELS / AQE	--	--Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification:

Yet To Be Classified
 --Select--
 Crew/Loco Operation
 Loco
 Stalling
 Traffic/wrongly logged
 Yet To Be Classified

 Railways (ZONE) Action Failure Responsible: --Select--

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

Save

To update failure responsibilities.

SLAM-TEST

Loco Failures - Locos - User Management

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
31098	WAG9H	Select	AQE	IOH	04/10/2023	ELS / AQE	IC	02/06/2023	ELS / AQE	--	--Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification: Yet To Be Classified Railways (ZONE) Action Failure Responsible:

--Select--
 Bad enginemen ship
 Bad enginemen ship
 Bad troubleshooting
 Bad Weather
 Bad Weather
 Cattle Run Over(CRO)/External Hitting
 Defective Design
 Defective Maintenance By Firm
 Defective Maintenance by Foreign shed (other than home shed)
 Defective Maintenance by Shed
 Defective Maintenance By Shop
 Defective Manufacture
 Defective Material By Firm
 Defective Material By Shed
 Defective Material By Shop
 Lack of Material
 Mal Operation By Crew/TLC
 Material Under Trial
 MISC

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

Save

To Update Zone Remarks.

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS/AQE Minor Sch.: IC Sch.Done On: 02/06/2023 Sch.Done At: ELS/AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking **Rly(ZONE)Action**

Classification: Yet To Be Classified Railways (ZONE) Action Failure Responsible: --Select--

Zonal Remark: TEST The grid is empty

Analysis Completed Analysis Not Required

Save

To click on Analysis Complete to close the Asset failure

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS/AQE Minor Sch.: IC Sch.Done On: 02/06/2023 Sch.Done At: ELS/AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking **Rly(ZONE)Action**

Classification: Yet To Be Classified Railways (ZONE) Action Failure Responsible: --Select--

Zonal Remark: TEST The grid is empty

Analysis Completed Analysis Not Required

Save

Click on Save.

After save 'Update' will be changed to 'View'.

Managing Asset Failure(ICMS)

Loco: Loco Kind: Loco Type: ICMS Sub Group: Equipment: Status: From: To: 01/03/2024


Showing 20 Record(s) Out of 1075

S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding.	Classification of Case	Home Rly	Equipment
1	16/10/2023 09:11 AM	EPFSTN	30799/WAP7		SER/CKP	TATA-GMH	TATA	T/NO.12262 EXP TATA ARRIVAL AT 09:11HRS,I/C LOCO NO.30799 (AJNI) DETAINING AT 09:15HRS,DUE TO LOCO TROUBLE AND FRESH LOCO NO.30594 TATA EOT AT 09:23HRS,HOG READY AT 09:28HRS,P/R- AT 09:34HRS,DEP- 09:40HRS.LOCO TROUBLE FROM KGR,TATA D/E NO.745.REP-12262 EXP LOSS 20'.			Loco	CR/NGP/AQE	View
2	15/10/2023 06:20 PM	ECRW	31408/WAG9H		NWR/BKN	BKN-SOG	SOG	E/BOXN LOCO NO-31408 WAITING FOR CREW AT SOG FROM 18/20 TO 20/50 HRS.			Yet To Be Classified	CR/NGP/AQE	Update
3	14/10/2023 08:36 PM	ELTP	32575/WAP7		NR/LKO	PBH-NEWC	SWPR-CHH	At 20:36 TM 11071/37575/AJNI IOH 13/08/23. Dn reported loco trouble, informed by LP in 11071 Dn in block section between SWPR-CHH . Informed to TLC/CNL train stopped at 20:36, LP attended, rectified and moved from site at 20:50 Hrs. Panto down it self. TM-Pankaj Kumar Srivastava/BSB M. no 9794833693			Yet To Be Classified	CR/NGP/AQE	Update
4	13/10/2023 11:47 PM	ELTP	30772/WAP7		NR/UMB	SGNR-RPJ	BTI	T.No-12138 DN BTI arrived 23:47 Hrs line No-04 DSL power 23:55 Hrs EP 30772 WAP-7 AQ IA 29/9 TI 10/10 POT 00:05 Hrs pressure not ready CLI/BTI attended P/Ready 00:22 Hrs, train departure 00:26 Hrs wrong confrigation, train 14 Min extra.			Yet To Be Classified	CR/NGP/AQE	Update
BYA DE NO.449 ON DATE 12/10/2023. LP OF 12860 REPORTED AT ABOUT													

SLAM Version - 4.0 ©2021 Centre for Railway Information Systems. All Rights Reserved. **CRIS**

2.2 Asset Failures (ICMS) Territorial

Click on asset failures ICMS Territorial under Loco failures



It shows the records of other than home shed divisions all the records can be shown in this ICMS Failures.

View Asset Failure (ICMS) Territorial

Loco: Loco Kind: Loco Type: ICMS Sub Group: Status: Shed(Ownership) From: To:

Enter all the required details and click on go option.

View Asset Failure (ICMS) Territorial

Loco: Loco Kind: Loco Type: ICMS Sub Group: Status: Shed(Ownership) From: To:

Showing 20 Record(s) Out of 318

S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding	Classification of Case	Home Rly	Equipment
1	07/01/2023 07:10 PM	EPOTH	31230/VAG9		WCR/JBP	MZHL-DRGM	MZHL-DRGM	JQSG LOCO NO.31230 AQ[BPC-DDU 02/01 PRE] MAJHAULI dep-19:10 detain due to load stall in section majhaulti-deoragram at km 1307/31 assiting loco no.60220 mzh dep-20:25 arrived at 20:54 attached at 20:56 dep -21:00 section clear at 21:18 ,rep-1 goods train			Yet To Be Classified	CR/NGP/AQ	Update
2	07/01/2023 10:40 AM	ELFG	32410/VAG9H		WCR/JBP	STA	STA	Train no up BCNE engine no 32410 BL from yard order at 10:40. engine 32410 failed by LI and shunter reversal handle is not available due to which KTE end throttle fail "			Yet To Be Classified	WR/BCT/BL	Update

Click on [Loco number link](#) to update HQ TLC Remarks.

Click on [Rly\(Zone\)Action link](#) to update Classification.

Update Line Failure

Defect Type: Occurrence On: Loco Unit: Multi Last Visit:

Loco: Type: Service: Base Shed: Major Sch.: Sch.Done On: Sch.Done At: Minor Sch.: Sch.Done On: Sch.Done At: TI Done on: TI Done At:

Occurrence Investigation Shed Report Attachments Failure Tracking **Rly(ZONE)Action**

Classification: Railways (ZONE) Action: Failure Responsible:

Zonal Remark:

Analysis Completed Analysis Not Required

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single / Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS / AQE Minor Sch.: IC Sch.Done On: 02/06/2023 Sch.Done At: ELS / AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification: Yet To Be Classified

Railways (ZONE) Action

Failure Responsible: --Select--

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

Save

To Update failure responsibilities.

SLAM-TEST

Loco Failures - Locomotives - User Management

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single / Multi Last Visit: S/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS / AQE Minor Sch.: IC Sch.Done On: -- Sch.Done At: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification: Yet To Be Classified

Railways (ZONE) Action

Failure Responsible: --Select--

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

Save

- Select--
- Bad enginemen ship
- Bad enginemen ship
- Bad troubleshooting
- Bad Weather
- Bad Weather
- Cattle Run Over(CRO)/External Hitting
- Defective Design
- Defective Maintenance By Firm
- Defective Maintenance By Foreign shed (other than home shed)
- Defective Maintenance by Shed
- Defective Maintenance By Shop
- Defective Manufacture
- Defective Material By Firm
- Defective Material By Shed
- Defective Material By Shop
- Lack of Material
- Mal Operation By Crew/TLC
- Material Under Trial
- MISC

To Update Zone remarks.

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single / Multi Last Visit: IOH- 04/10/2023 - ELS/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS / AQE Minor Sch.: IC Sch.Done On: 02/06/2023 Sch.Done At: ELS / AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking Rly(ZONE)Action

Classification: Yet To Be Classified

Railways (ZONE) Action

Failure Responsible: --Select--

Zonal Remark: TEST

Analysis Completed Analysis Not Required

Save

To click on Analysis Complete to close the asset failure

Update Line Failure

Defect Type: --Select-- Occurrence On: 15/10/2023 22:21 Loco Unit: Single Multi Last Visit: IOH-04/10/2023 - ELS/AQE

Loco: 31098 Type: WAG9H Service: Select Base Shed: AQE Major Sch.: IOH Sch.Done On: 04/10/2023 Sch.Done At: ELS/AQE Minor Sch.: IC Sch.Done On: 02/06/2023 Sch.Done At: ELS/AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking **Rly(ZONE)Action**

Classification: Yet To Be Classified Railways (ZONE) Action: Failure Responsible: --Select--

Zonal Remark: The grid is empty

Analysis Completed Analysis Not Required

[Save](#)

Click to Save Button

Line Failures

slam.indianrail.gov.in/SLAMTEST/Locs/lcmsAssetFailuresAddEdit.aspx?id=200699

Loco Failures - Locos - User Management

Update Line Failure

Defect Type: EPFSTN Occurrence On: 16/10/2023 09:11 Loco Unit: Single Multi Last Visit: TI-03/10/2023 - TS/HT

Loco: 30799 Type: WAP7 Service: Select Base Shed: AQE Major Sch.: TOH Sch.Done On: 30/03/2023 Sch.Done At: ELS/AQE Minor Sch.: IB Sch.Done On: 14/09/2023 Sch.Done At: ELS/AQE TI Done on: -- TI Done At: --Select--

Occurrence Investigation Shed Report Attachments Failure Tracking **Rly(ZONE)Action**

Classification: Loco Railways (ZONE) Action: Failure Responsible: MISC

Zonal Remark:

S.No	Date	Fun Loc.	Classification	Failure Responsible	Zonal Remark
1	01-03-2024 12:12 PM	CR	Loco	MISC	test

Analysis Completed Analysis Not Required

[Update](#) [Back](#)

SLAM Version - 4.0 ©2021 Centre for Railway Information Systems. All Rights Reserved. CRIS

After save 'Update' will be changed to 'View'

Managing Asset Failure(ICMS)

Loco: Loco Kind: -- All -- Loco Type: ICMS Sub Group: Equipment: Status: -- All -- From: 01/03/2024 To: 00

Showing 20 Record(s) Out of 1075


S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding.	Classification of Case	Home Rly	Equipment
1	16/10/2023 09:11 AM	EPFSTN	30799/WAP7		SER/CKP	TATA-GMH	TATA	T/NO.12262 EXP TATA ARRIVAL AT 09:11HRS,I/C LOCO NO.30799 (AJNI) DETAINING AT 09:15HRS,DUE TO LOCO TROUBLE AND FRESH LOCO NO.30594 TATA EOT AT 09:23HRS,HOG READY AT 09:28HRS,P/R- AT 09:34HRS,DEP-09:40HRS,LOCO TROUBLE FROM KGR:TATA D/E NO.745.REP-12262 EXP LOSS 20".			Loco	CR/NGP/AQE	View
2	15/10/2023 06:20 PM	ECRW	31408/WAG9H		NWR/BKN	BKN-SOG	SOG	E/BOXN LOCO NO-31408 WAITING FOR CREW AT SOG FROM 18/20 TO 20/50 HRS.			Yet To Be Classified	CR/NGP/AQE	Update
3	14/10/2023 08:36 PM	ELTP	37575/WAP7		NR/LKO	PBH-NEWC	SWPR-CHH	At 20:36 TM 11071/37575/AJNI IOH 13/08/23. Dn reported loco trouble, informed by LP in 11071 Dn in block section between SWPR-CHH . informed to TLC/CNL train stopped at 20:36, LP attended, rectified and moved from site at 20:50 hrs. Panto down it self. TM-Pankaj Kumar Srivastava/BSS M. no 9794833693			Yet To Be Classified	CR/NGP/AQE	Update
4	13/10/2023 11:47 PM	ELTP	30772/WAP7		NR/UMB	SGNR-RPJ	BTI	T.No-12138 DN BTI arrived 23:47 Hrs line No-04 DSL power 23:55 Hrs EP 30772 WAP-7 AQ IA 29/9 TI 10/10 POT 00:05 Hrs pressure not ready CLI/BTI attended P/Ready 00:22 Hrs, train departure 00:26 Hrs wrong confrigation, train 14 Min extra.			Yet To Be Classified	CR/NGP/AQE	Update
BVA DE NO 449 ON DATE 12/10/2023. LP OF 12860 REPORTED AT ABOUT													

SLAM Version - 4.0 ©2021 Centre for Railway Information Systems. All Rights Reserved. CRIS


3. Locos

3.1 Find a Loco

- Click on Find a loco menu under Locos side menu.
- Find a loco page displays.



- Enter the Loco Number and click on Go option.



3.2 Loco History

In this page, Loco History details like Loco Number, Inward Date, Purpose of Visit, Description and Completed Date etc., are displayed.

- Click on "Locos" side menu and select "Loco History" navigation menu.
- "View Loco History" page is displayed.
- Select Location, Loco, From and To dates, click on button to view the Loco History details.

View Loco History

Select For Location Loco Description From To Purpose
 --All-- --All-- 31573 30/08/2022 Go

Loco Details					
DoC:	26/04/15 00:00	Type:	WAG9H	Last Minor:	IC-10/06/22
Last Major:	IOH-13/10/20	Next Due:	IT-25/07/22	Last POH Done:	--
Next Minor:	IT-25/07/22	Next Major:	NA	Status:	In Use

Showing 20 Records Out of 82

Loco	Activity Date	Purpose	Description	Dt. Completed	Location	
31573	07/08/2022 13:05	UnSch	PPO	Arrived - BG 2 ISO	18/08/2022 04:15	ELS/AQ
			PPO	Dispatched - N		
31573	02/08/2022 06:10	UnSch	PPO	Arrived - BG 2 ISO	06/08/2022 16:35	ELS/AQ
			PPO	Dispatched - N		
31573	25/07/2022 16:55	UnSch	PPO	Arrived - LC 2 BG 2 ISO. U/ABB	01/08/2022 14:00	ELS/AQ
			PPO	Dispatched - NORMAL,		
31573	20/07/2022 07:28	INF	Failed Sec: Occurrence: BG 2 ISO Initial Action Taken:		--	ELS/AQ