


## Asset Failures (ICMS) Territorial

Click on asset failures ICMS Territorial under Loco failures



It shows the records of other than home shed divisions all the records can be shown in this ICMS Failures.

**View Asset Failure (ICMS) Territorial**

Loco:  Loco Kind:  Loco Type:  ICMS Sub Group:  Status:  Shed(Ownership) From:  To:

Enter all the required details and click on go option.

**View Asset Failure (ICMS) Territorial**

Loco:  Loco Kind:  Loco Type:  ICMS Sub Group:  Status:  Shed(Ownership) From:  To:

Showing 20 Record(s) Out of 318

| S.No | Date                   | Sub Heading | Loco No.                     | Train No. | Reported in Rly(Territorial) | Major Section/Stn | Minor Section/Stn | ICMS Report  | Action Plan | Brief Finding | Classification of Case | Home Rly  | Equipment              |
|------|------------------------|-------------|------------------------------|-----------|------------------------------|-------------------|-------------------|--|-------------|---------------|------------------------|-----------|------------------------|
| 1    | 07/01/2023<br>07:10 PM | EPOTH       | <a href="#">31230/V/AG9</a>  |           | WCR/JBP                      | MZHL-DRGM         | MZHL-DRGM         | JQSG LOCO NO.31230 AQ[BPC-DDU 02/01 PRE] MAJHAULI dep-19:10 detain due to load stall in section majhaulti-deoragram at km 1307/31 assiting loco no.60220 mzh dep-20:25 arrived at 20:54 attached at 20:56 dep -21:00 section clear at 21:18 ,rep-1 goods train |             |               | Yet To Be Classified   | CR/NGP/AQ | <a href="#">Update</a> |
| 2    | 07/01/2023<br>10:40 AM | ELFG        | <a href="#">32410/V/AG9H</a> |           | WCR/JBP                      | STA               | STA               | Train no up BCNE engine no 32410 BL from yard order at 10:40. engine 32410 failed by LI and shunter reversal handle is not available due to which KTE end throttle fail "  |             |               | Yet To Be Classified   | WR/BCT/BL | <a href="#">Update</a> |

Click on [Loco number link](#) to update tracking details

Enter all the details which are required.

Click on save option.

**Update Tracking Information**
X

Loco Number

Current Division

Present Location  Status On

Current Position

Loco Condition  Working/P.DEF  Dead/INF  LE

ADD

| Division | Location | Status On        | Condition     | Position |
|----------|----------|------------------|---------------|----------|
| BSP      | sbk      | 09/01/2023 17:57 | Working/P.DEF | working  |

Attended On Line by  
 Arrived Home Shed & Attended  
 Arrived Home Shed & Not Attended  
 None

Save

Click on [Update](#) link to update line failures details.

Administration Bulletin Boards Corrections Loco Abnormalities Loco Failures Locos Memos Movement Register Notes(0) Planning User Management

**Update Line Failure**

Defect Type  Occurrence On  Loco Unit  Last Visit:

Loco  Type  Service  Base Shed  Major Sch.  Sch. Done On  Sch. Done At  Minor Sch.  Sch. Done On  Sch. Done At  TI Done on  TI Done At

Occurrence  Investigation  Shed Report  Attachments

Section/Station Of Occurrence  Zone  Division

Train No  Station (After)  Station (Before)

Direction  Gradient  Load

Detention  Repurcussion  Punct Loss

Wagons / Coaches  No. of Units  Loco Condition  (To be filled by TLC)

Service Withdrawal  Withdrawal Place  Withdrawal On

Section KM/Pole No  Reported  Division  HQ  RB  E&R

Line Attention Taken  
(To be filled by TLC)

CMS Remarks

\*11020EXP 01:03\* VSKP[22:05-23:33] EXTRA FOR O/G POWER(37588/BZA) PANTOGRAPH IS NOT RAISING, AS PER TLC/CHG MEMO TO CHANGE THE LOCO FOR O/G AT 22:50HRS. ANOTHER POWER ARRANGED AT 23:07HRS EOT 23:10HRS HOG COMPLETED AT 23:25HRS AND

Update
Back

SLAM Version - 4.0 ©2021

Line Attention taken and Loco Condition To Be filled up.

Click on update.