

TS Loco Movement History

Once the final disposal of the loco has been done from TLC, its details can be viewed in "TS Movement History" form.

- Click on "TS Loco Movement" sub menu under "Movement Register" side menu
- "View TS Movement History" screen will be displayed.




Image – 1

View TS Movement History

Loco From To

- By filtering the Loco Number, From Date and To Date, click on Button, tabular form is generated as shown in the below image.

View TS Movement History																							
Loco		From		To																			
<input type="text"/>		<input type="text"/>		<input type="text" value="13/09/2023"/>																			
S.No	Loco	Base Shed	Purpose	SPM (KM)	TLC UOR Remarks	Loco Received Station	Arrival Condition	TLC Sent Date	Maintenance Location Details				Loco Out Time	Loco On to Traffic (from TLC)	Log Book/UOR		Remarks	Action Taken					
									Received at TS	Pit In	Pit Out				Defect	Action Taken		Under Frame	M.T. Machine Room	Pneumatic	Others	Roof Equipment	Cab Equipment
1	22212	B5LL	TI	20281				..	23/07/2023	24/07/2023	24/07/2023	24/07/2023	24/07/2023	CAB 1 SIDE WINDOW GLASS BROKION CONDITION	ATTENDED BY LCC/RTM STAFF	LOCO GIVEN TO READY FOR TLC AFTER TI	BOTH CAB SANDRES ATTENDED	WSM CHANGED	HAND BREAK ATTENDED	BPEMS SWITCH WIRING FOUND EARTH WITH BL BOX SAME ATTENDED			
2	25028	RTND	TI	8066				..	24/07/2023	24/07/2023	24/07/2023	24/07/2023	24/07/2023	CAB 1 ALP SIDE SPOT LIGHT NOT GLOWING	TO BE ATTEND TO HOME SHED	LOCO GIVEN TO READY FOR TLC AFTER TI							
3	22619	SPJD	TI	1578188				..	23/07/2023	23/07/2023	23/07/2023	23/07/2023	23/07/2023	TFS BRITHORE VALVE OIL LEAKEGE	BRITHORE VALVE CILUCA GEL CHENGED	LOCO GIVEN TO READY FOR TLC AFTER TI	HAND BREAK DEFECTIVE ATTENDED BY LCC/RTM STAFF						
4	22383	RTND	TI	34954				..	23/07/2023	23/07/2023	23/07/2023	23/07/2023	23/07/2023	HVCD SWITCH FOUND SEALED CONDITION		LOCO GIVEN TO READY FOR TLC AFTER TI							
5	31551	BLEE	TI	153386				..	22/07/2023	22/07/2023	22/07/2023	22/07/2023	22/07/2023	CAB 2 SIDE CLAVIS HENDLE FOUND BROKEN CONDITION	ATTENDED	LOCO GIVWN TO READY FOR TLC AFTER TI							

Image - 2