

TLC Loco Failures – View Line Failures

- The added line failures are shown in "Managing Line Failures" page.
- Enter Loco number, select Type, Status, Division, Railway Zone, From and To Date to view the Line Failures.

Managing Line Failures

Managing Line Failures

[Add Line Failure](#)

Loco Loco Kind Loco Type Type Status Zone Division Equipment Failure Group Failure SubGroup

Equipment Make Failure Responsibility LF Status Station of Occurance From To

Showing 20 Record(s) Out of 21538

S.No	Loco	Defect	Date	FailureGroup	FailureResponsibility	Occurrence	Section Of Occurrence	Attention	Detention	Sch	Inward On	Added By	Online Att Loc	Delete
1	90006	INF	27/10/2022 01:00 AM			DJ NOT HOLD & HARMONIC FILTER CONTACTOR STUCK UP LOCO AT ANVT U/CHECKING BY SIEMENS,SIEMENS-PROP.	ANVT	ELS/TKD Update	NDLS/TS	
2	90003	P.DEF	26/10/2022 10:00 PM			BOGIE-1 ISOLATE LOCO WKG RNO/BRC DIV. BHEL- PROP.	GGC	ELS/TKD Update		

TLC Loco Failures – Line Failures

- Online defects (out of shed) are captured, saved and displayed in Line Failure list.
- In the "Add Line Failures" page, fill in the mandatory details by clicking the following tabs –
 1. Occurrence
 2. Crew/Loco Pilot
 3. Punctuality
 4. Parting
 5. BPC (Break Power Certificate)
 6. Attachments

Add Line Failures - Occurrence

Add Line Failure

Defect Type: Occurrence On: Loco Unit: Single Multi Last Visit: **IT- 10/10/2022 - ELS/GMO**

Loco: Type: Service: Base Shed: Major Sch.: Sch.Done On: Sch.Done At: Minor Sch.: Sch.Done On: Sch.Done At: TI Done on: TI Done At:

Section/Station Of Occurrence: Zone: Division:

Train No: Station (After): Station (Before):

Direction: Gradient: Load: (Tons)

Detention: Repurcussion: Punct.Loss:

Failure Cause (Reported): Wagons / Coaches: (No) No. of Units: (No)

Service Withdrawal: Withdrawal Place: Withdrawal On:

Section KM/Pole No: Reported: Division HQ RB E&R

Occurrence: Line Attention Taken:

Add Line Failures – Crew/Loco Pilot

Add Line Failure

Defect Type: Occurrence On: Loco Unit: Single Multi Last Visit: **IT- 10/10/2022 - ELS/GMO**

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
<input type="text" value="31000"/>	<input type="text" value="WAG"/>	<input type="text" value="Good"/>	<input type="text" value="GMO/E"/>	<input type="text" value="IOH"/>	<input type="text" value="17/02/2021"/>	<input type="text" value="ELS / GM"/>	<input type="text" value="IT"/>	<input type="text" value="10/10/2022"/>	<input type="text" value="ELS / GM"/>	<input type="text"/>	<input type="text" value="--Select--"/>

Occurrence Crew/Loco Pilot Punctuality Parting BPC Investigation CTA Report Shed Report HQ Report Attachments Tracking Failure Tracking

Crew HQ: Beat Section:

LI Name: LI ID: Last Foot Plate Inspection:

Name	Crew ID	Designation	Grade	Last Coun. Date	Exp. Deatils
<input type="text" value="Crew1/LP1"/>	<input type="text"/>	<input type="text" value="LOCO PILOT"/>	<input type="text" value="A"/>	<input type="text"/>	<input type="text"/>
<input type="text" value="Crew2/LP2"/>	<input type="text"/>	<input type="text" value="LOCO PILOT"/>	<input type="text" value="B"/>	<input type="text"/>	<input type="text"/>

Add Line Failures - Punctuality

Add Line Failure

Defect Type Occurrence On Loco Unit Single Multi Last Visit: **IT- 10/10/2022 - ELS/GMO**

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
<input type="text" value="31000"/>	<input type="text" value="WAG"/>	<input type="text" value="Good"/>	<input type="text" value="GMO/E"/>	<input type="text" value="IOH"/>	<input type="text" value="17/02/2021"/>	<input type="text" value="ELS / GM"/>	<input type="text" value="IT"/>	<input type="text" value="10/10/2022"/>	<input type="text" value="ELS / GM"/>	<input type="text"/>	<input type="text" value="--Select--"/>

Occurrence	Crew/Loco Pilot	Punctuality	Parting	BPC	Investigation	CTA Report	Shed Report	HQ Report	Attachments	Tracking	Failure Tracking
------------	-----------------	--------------------	---------	-----	---------------	------------	-------------	-----------	-------------	----------	------------------

Detention Details

Train No	Duration	Result	Type	T/O Station	T/O Late	H/O Station	H/O Late
<input type="text"/>	<input type="text" value="(HH:MM)"/>	<input type="text" value="LT"/>	<input type="text" value="--Select--"/>	<input type="text"/>	<input type="text" value="(HH:MM)"/>	<input type="text"/>	<input type="text" value="(HH:MM)"/>

Repercussion Details

Add Line Failures - Parting

Add Line Failure

Defect Type: Occurrence On: Loco Unit: Single Multi Last Visit: **IT- 10/10/2022 - ELS/GMO**

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
<input type="text" value="31000"/>	<input type="text" value="WAG"/>	<input type="text" value="Good"/>	<input type="text" value="GMO/E"/>	<input type="text" value="IOH"/>	<input type="text" value="17/02/2021"/>	<input type="text" value="ELS / GM"/>	<input type="text" value="IT"/>	<input type="text" value="10/10/2022"/>	<input type="text" value="ELS / GT"/>	<input type="text"/>	<input type="text" value="--Select--"/>

Coach/Wagon Details (In case Of Loco Parting)

Parting Reason:

Type Of Rake: Position From Engine: Position From Guard Coach:

Coach/Wagon 1 Details

Wagon No1:

Last Major Sch.: Sch.Done On: Sch.Done At:

Last Minor Sch.: Sch.Done On: Sch.Done At:

Coach/Wagon 2 Details

Wagon No2:

Last Major Sch.: Sch.Done On: Sch.Done At:

Last Minor Sch.: Sch.Done On: Sch.Done At:

Add Line Failures – BPC(Break Power Certificate)

Add Line Failure

Defect Type Occurrence On Loco Unit Single Multi Last Visit: **IT- 10/10/2022 - ELS/GMO**

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
<input type="text" value="31000"/>	<input type="text" value="WAG"/>	<input type="text" value="Goodt"/>	<input type="text" value="GMO/E"/>	<input type="text" value="IOH"/>	<input type="text" value="17/02/2021"/>	<input type="text" value="ELS / GM"/>	<input type="text" value="IT"/>	<input type="text" value="10/10/2022"/>	<input type="text" value="ELS / GM"/>	<input type="text"/>	<input type="text" value="--Select--"/>

Occurrence Crew/Loco Pilot Punctuality Parting **BPC** Investigation CTA Report Shed Report HQ Report Attachments Tracking Failure Tracking

Break Power Certificate Details (For Full Train)

Issued Station Issued Division

Issued On Break Power Percentage (0 to 100) Certificate No

Add Line Failures - Attachments

Add Line Failure

Defect Type: Occurrence On: Loco Unit: Single Multi Last Visit: [IT- 10/10/2022 - ELS/GMO](#)

Loco: Type: Service: Base Shed: Major Sch.: Sch.Done On: Sch.Done At: Minor Sch.: Sch.Done On: Sch.Done At: TI Done on: TI Done At:

Occurrence Crew/Loco Pilot Punctuality Parting BPC Investigation CTA Report Shed Report HQ Report **Attachments** Tracking Failure Tracking

Name:

Document: No file chosen

Remarks:

Available Documents

TLC Line failures– Update Line Failures

- Necessary details are updated by clicking on "Update" link in "Managing Line Failures" page.
- "Update Line Failures" page is shown, update the required fields and save the details.

Update Line Failures

Update Line Failure

Defect Type Ineffective/De **Occurrence On** 27/10/2022 01:00 **Loco Unit** Single **Last Visit:** IB- 26/10/2022 - ELS/TKD

Loco	Type	Service	Base Shed	Major Sch.	Sch.Done On	Sch.Done At	Minor Sch.	Sch.Done On	Sch.Done At	TI Done on	TI Done At
90006	WAG	Good	TKD	Select	--	--Select--	Sel	--	--Select--	--	--Select--

Occurrence
Crew/Loco Pilot
Punctuality
Parting
BPC
Investigation
CTA Report
Shed Report
HQ Report
Attachments
Tracking
Failure Tracking

Section/Station Of Occurrence	ANVT	Zone	NR	Division	DLI
Train No		Station (After)	--Select--	Station (Before)	--Select--
Direction	--Select--	Gradient	Select	Load	(Tons)
Detention	--Select--	Repurcussion	--Select--	Punct.Loss	No
Failure Cause (Reported)	---Select---	Wagons / Coaches	0 (No)	No.of Units	0 (No)
Service Withdrawal	--Select--	Withdrawal Place		Withdrawal On	
Section KM/Pole No		Reported	<input type="checkbox"/> Division <input type="checkbox"/> HQ <input type="checkbox"/> RB <input type="checkbox"/> E&R		

Occurrence
 DJ NOT HOLD & HARMONIC FILTER CONTACTOR STUCK UP LOCO AT ANVT U/CHECKING BY SIEMENS,SIEMENS-PROP.

Update
Back

Asset Failures ICMS (Ownership)

- It shows all the failed locos of our division (Home shed). ICMS Failures which can be updated in that particular division.

View Asset Failure (ICMS) Ownership

Loco Loco Kind Loco Type ICMS Sub Group Status Zone(Territorial) Division(Territorial) Shed(Ownership) From To

--All-- --Select-- --All-- --All-- --All-- --All-- --All-- --All-- 09/01/2023 Go

Showing 20 Record(s) Out of 46

S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding	Classification of Case	Home Rly	Equipment
1	08/01/2023 04:00 AM	ONCR	23351/1/AG5		DFCC/EDFC	SJTN-SJTN	SJTN-SJTN	KN-22/23351/3557 TRAIN IS CONTROLLED DUE TO SLOW RECEPTION BY IR SJT			Yet To Be Classified	WCR/JBP/NKJ(D)	Update
2	08/01/2023 03:15 AM	ELFG	23887/1/AG5T		NR/DLI	JIND	JIND	MKS/FBD POWER NO-23887+23639 AFTER PASSING STR STOP THE LOAD AND LOCO TROUBLED REP 19803/ 12138 SUFFERD			Yet To Be Classified	WCR/JBP/NKJ(D)	Update
3	07/01/2023 06:15 PM	ECRW	27114/1/AG7		NWR/BKN	KSI	KSI	TKD WITH DSL 27114 AT KSI, FOR CREW, FROM 18/15 TO 00/00 HRS.			Yet To Be Classified	WCR/JBP/NKJ	Update
4	07/01/2023 10:25 AM	ELTG	23786/1/AG5		NER/BSB	GKC-CPR	CPR	DN AZA/23786+23668/NKJ/13/2 CPR arrived at 10.25 out at 13.10.detained due to power trouble U1, U2, A3 miter not working and VCD isolated fault in 2nd LOCO while DJ holding same attached by CLI.			Yet To Be Classified	WCR/JBP/NKJ(D)	Update

Asset Failures ICMS (Territorial)

- It shows all the failed locos in our divisions.

View Asset Failure (ICMS) Territorial

Loco: Loco Kind: -- All -- Loco Type: -- Select -- ICMS Sub Group: -- All -- Status: -- All -- Shed(Ownership) From: To: 09/01/2023

Showing 20 Record(s) Out of 318

S.No	Date	Sub Heading	Loco No.	Train No.	Reported in Rly(Territorial)	Major Section/Stn	Minor Section/Stn	ICMS Report	Action Plan	Brief Finding	Classification of Case	Home Rly	Equipment
1	07/01/2023 07:10 PM	EPOTH	31230/WAG9		WCR/JBP	MZHL-DRGM	MZHL-DRGM	JQSG LOCO NO.31230 AQ[BPC-DDU 02/01 PRE] MAJHAULI dep-19:10 detain due to load stall in section majhauli-deoragram at km 1307/31 assiting loco no.60220 mzhl dep-20:25 arrived at 20:54 attached at 20:56 dep -21:00 section clear at 21:18 ,rep-1 goods train			Yet To Be Classified	CR/NGP/AQ	Update
2	07/01/2023 10:40 AM	ELFG	32410/WAG9H		WCR/JBP	STA	STA	Train no up BCNE engine no 32410 BL from yard order at 10:40. engine 32410 failed by LI and shunter reversal handle is not available due to which KTE end throttle fail "			Yet To Be Classified	WR/BCT/BL	Update