

Repair sheet history


The Repair sheets of all the equipment is shown in "Repair Sheet History" page. The Repair sheet details include equipment name, equipment number, Removed on and Ready on dates, Maintenance Place.

i. **View Repair Sheet History:**

To view the repair sheet history,


Click on "Shop Floor" side menu and select "Repair Sheet History" navigation menu.


"Repair Sheet History" page is shown.



The screenshot shows the "Repair Sheet History" filter form. It includes a dropdown menu for "Eq.Name" with "--All--" selected, and input fields for "Eq.Number(M)", "Eq.Number(L)", "From", and "To". The "To" field contains the date "06/08/2022". A "Go" button is located to the right of the "To" field.

Repair Sheet History

On filtering the options such as Loco, Section and by clicking on  button, Repair Sheets related to equipment are displayed in a tabular format.



The screenshot shows the "Repair Sheet History" table. The table has 10 columns: S.No, Sheet No, Eq.Name, Eq.Number(M), Eq.Number(L), Removed On, Ready On, Maintenance Place, Lifted On, and Received On. The table contains 7 rows of data. The "Go" button from the filter form is visible at the top right of the table area.

S.No	Sheet No	Eq.Name	Eq.Number(M)	Eq.Number(L)	Removed On	Ready On	Maintenance Place	Lifted On	Received On
1	5115	DE BEARING	tkd1	tkd1	23/11/2019	--	Shop Floor	--	--
2	5539	DE BEARING	2	0	23/07/2020	--	Shop Floor	--	--
3	5538	DE BEARING	1	1	23/07/2020	--	Shop Floor	--	--
4	5540	NDE BEARING			23/07/2020	--	Shop Floor	--	--
5	4109	PE Bearing	TKD-180	TKD-180	05/01/2018	--	Shop Floor	--	--
6	2376	TM ARM HITACHI	HA-586/SKE-430	HA-586/SKE-430	24/08/2016	31/10/2014	Shop Floor	--	--
7	2539	TM ARM HITACHI	H-1211/S-115	1399	20/09/2016	17/10/2016	Shop Floor	--	--

Repair Sheet History

On clicking the Sheet Number link, user is navigated to "Equipment Repair Sheet" page.

Equipment Repair Sheet - 5115

Equipment Details

Eq.Name :	DE BEARING	Eq.Number :	tkd1	Make :	AAL
Loco :	--	Reason For Removal :	--	Removal Date :	--
DoC :	01/11/2019	Abnormality :	--	Warranty :	--

Repair Status | Sub Process | Test Profile | Attachments | Notes | Consumed Materials

Repair Sheet Status: Ready | Maintenance Done At: Shop Floor | Assembly Status: Full

Equipment Status: Ready | Ready Date: | Next Overhaul Date:

Proposed For Condemnation

Type of Repair: General Checkup

Technician Attended: Ajab Singh/A923

Remarks:

Equipment Repair Sheet