

Unit Exchange Spares

This page shows the list of equipment such as good spare, defective material at firm as well as shop floor. It also gives detailed description about the status of each equipment.

i. View Unit Exchange Spares:

In "Unit Exchange Spares" page, the list of equipment and its details are shown.

Unit Exchange Spares

Section Eq. Category Eq. Name

Click on "Shop Floor" side menu and select "Unit Exchange Spares" navigation menu.

On filtering the options such as Section, equipment Category, equipment name and by clicking on button, equipment details related to the section are displayed in a tabular format.

Unit Exchange Spares																				
Section <input type="text" value="M3HR"/> Eq. Category <input type="text" value="--All--"/> Eq. Name <input type="text"/> <input type="button" value="Go"/>																				
S.No	Eq.Name	Population	InUse	UES	Due For Loco	Good Spare					Defective at Shop Floor					Defective at Firm			Total Deff.	Total Spares
						Ready	Partial Ready	U/OH	W.F.OH	Sub Total	W.F.Mtr	W.F.Firm	W.F.W.A	P.Cond	Sub Total	U/W.Atten	U/F.Atten	Sub Total		
1	CE Bearing	2	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2	DE BEARING	15	15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3	NDE BEARING	14	14	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4	PE BEARING	1	0	1	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0
5	PINION	30	30	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6	PINION 3-PH	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	TM ARM HITACHI	134	59	59	16	4	0	21	0	75	0	0	0	0	0	0	0	0	0	75
8	TM ARM TAO	492	226	79	187	13	0	253	0	266	0	0	0	0	0	0	0	0	0	266
9	TM ROTOR G9P7	1227	1200	-80	107	1	0	26	0	27	0	0	0	0	0	0	0	0	0	27
10	TM SS	24	0	0	24	1	0	23	0	24	0	0	0	0	0	0	0	0	0	24
11	TM STAT HITACHI	117	59	52	6	0	0	58	0	58	0	0	0	0	0	0	0	0	0	58
12	TM STAT TAO	576	218	175	183	1	1	338	0	340	0	0	0	18	18	0	0	0	18	358
13	TM TEMP SENSOR	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
14	Traction Motor G9P7	1386	1270	84	32	13	1	102	0	116	0	0	0	0	0	0	0	0	0	116

Click on the number links in the columns such as Ready, Partial ready,

- U/OH - Under overhauling,
- W.F.OH - Waiting for overhauling,
- W.F.Mtr - Waiting for material,
- W.F.Firm - Waiting for Firm attention and
- W.F.W.A - Waiting for warranty attention,
- P.Cond - Partial Condemn,
- U/Warranty attention,
- U/Firm .Atten- Under Firm attention to navigate the "Repair sheets" page.

Repair Sheets

Eq.Name: TM ARM HITACHI | Make: --All-- | Eq.Number(M): | Eq.Number(L): | From: | To: 06/08/2022 | Status: Under Repair | Go

Showing 20 Record(s) Out of 71

S.No	Sheet No	Eq. Name	Loco Type	Eq.Number(M)	Eq.Number(L)	Make	Removed On	Status	Remarks
1	1613	TM ARM HITACHI	WCAM3,WAG7,WAG5H,WCAG1,WAP4,WCAM2,WCM6	08-02--8802	1741	CLW	06/03/2016	Under Repair	
2	3448	TM ARM HITACHI	WAP4,WAG7,WCAG1,WCAM2,WCM6,WCAM3,WAG5H	11055/C843	2228	CLW	29/04/2017	Under Repair	
3	1492	TM ARM HITACHI	WCAM2,WCM6,WCAM3,WAG5H,WAP4,WAG7,WCAG1	11789/M437	2264	CLW	27/05/2015	Under Repair	
4	3212	TM ARM HITACHI	WCAG1,WCAM2,WAP4,WCM6,WCAM3,WAG5H,WAG7	1248/N/92	1402	CLW	14/02/2017	Under Repair	
5	3833	TM ARM HITACHI	WCAG1,WCM6,WCAM2,WAG5H,WAG7,WAP4,WCAM3	12496/M-816	12496/M-816	CGL	17/08/2017	Under Repair	
6	1686	TM ARM HITACHI	WCM6,WAG5H,WAG7,WCAM3,WCAG1,WCAM2,WAP4	13096/N/36	2203	CLW	20/01/2014	Under Repair	
7	1615	TM ARM HITACHI	WCAG1,WAP4,WCM6,WCAM2,WAG5H,WAG7,WCAM3	1641/A107	1310	CLW	06/03/2016	Under Repair	

Click on the sheet number link to view the corresponding repair sheet.

Equipment Repair Sheet - 1613

Equipment Details

Eq.Name : TM ARM HITACHI | Eq.Number : 08-02--8802 | Make : CLW
 Loco : -- | Reason For Removal : -- | Removal Date : --
 DoC : 21/07/2008 | Abnormality : -- | Warranty : --

Repair Status: **Partial ready** | Maintenance Done At: Shop Floor | Assembly Status: Full

Equipment Status: Ready | Ready Date: 06/08/2022 | Next Overhaul Date: | Proposed For Condemnation

Type of Repair: General Checkup

Technician Attended: Ajab Singh/A923

Remarks: ready for use

Save | Back